# University of Otago Detailed Risks - All - Construction and Maintenance Report Period 01/01/1970 to 31/12/2037



#### **Asbestos**

ID 8379 Alert Number CRITICAL RISK Next Review 31/01/2024
GPS Longitude GPS Latitude Location
Category Construction Reported By Karen Bonney Significant Risks Yes
Site Asbestos (Critical Risk) Date 10/06/2021 Status Underway

Description Risk of illness due to exposure to asbestos in buildings.

Pleural plaques, asbestosis and mesothelioma.

Old buildings with a high likelihood of containing asbestos - demolition or routine maintenance may expose

staff to asbestos fibres.

#### **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Work processes	Operating procedures not followed	Potential for illness
Chemical	Hazardous Chemicals	Body contact/exposure	Potential illness

#### **Risks Identified**

Risk	Risk/Score
	- High

#### Residual Risk Rating 5.00

Type	Control	Control Name	Status	Description
Modified	Administrative Controls	Education		Training includes awareness of asbestos and processes to follow. Education sessions for building occupiers where asbestos is identified.
		Internal Policy and/or Guidelines		Asbestos information and awareness of building ages and likelihood of asbestos in buildings. Guidelines on what to do if you suspect asbestos content in building.  Asbestos removal programme to eliminate asbestos from buildings.
	Administrative Controls	Personal or environmental monitoring		Personal or environmental monitoring is available when asbestos is suspected or during clean up and removal. Contact Property Services.
	Controls	Removal of asbestos by approved external contractors	Completed	Only certified asbestos removers can remove asbestos.
		Building surveys to identify asbestos		Send sample for testing to verify if asbestos and what type. Area must be sealed off until testing completed, if removal required must be completed by external certified contractor.
	Administrative Controls	Management		Contact Property Services with any concerns regarding asbestos in buildings. Staff notified of potential or actual Asbestos before work commencing. Register of known asbestos locations available to all PS staff.
New	Administrative Controls	Signage		Signage and labelling of asbestos containing materials.
		Asbestos discovery flow chart		notification process in place for staff (trade services and contractors) working with asbestos

#### **Reviews**

31/03/2023 10:20:58 Page:1 of 16

Date	Person	Findings	Actions	Status
11/06/2021	Karen Bonney	Updated controls		Completed
31/01/2023	Karen Bonney	Added flow chart in files		Completed

## **Height Work**

ID 8380

Alert Number CRITICAL RISK

Next Review 31/01/2024

GPS Longitude

**GPS** Latitude Reported By Karen Bonney

Location Significant Risks Yes

Category Construction

Site Height Work (Critical Risk) Date 11/06/2021 Status Completed

Description Fall from height resulting in injury

Items falling from height. Unprotected edges

Unsuitable working environment

- slippery roof

- brittle roof

- adverse weather conditions (wind and rain)

Unsecured equipment

Inappropriate use of access and or fall arrest equipment

- ladders

- scaffold

- elevated work platform

- harness and lanyards

- anchor points

- sky lights

- steep areas



Scafftag or aculog.

Collapsed scaffold with inadequate outrigger props, on soft ground, in the wind.



# **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Working at height/ladder use	Risk of trip	Personal Injury/fatality
Physical	Working at height/ladder use	Risk of items falling	injury to others
Physical	Working at height/ladder use	Risk of fall	Personal Injury/fatality

#### **Risks Identified**

Risk	Risk/Score	
	- Very High	·

31/03/2023 10:20:58 Page:2 of 16

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
	Engineering Controls	Security	Completed	Where height working is required, ensure secure so that unauthorised access prevented. Always check height equipment prior to starting your days work.
Modified		Height Safety and Fall arrest training	Completed	All staff required to work at heights to be trained in safe methods of height working and specifics on the methods in use. Staff trained in the permit to work system. NZQA17600
Modified		Internal Policy and/or Guidelines including Permit to Work at Height	Completed	Permit to work system for height work over 3 metres. Contractor management policy and process.
Modified		Planned maintenance/checks for height equipment	Completed	Plans for regular maintenance or checks are in place for height equipment.  Worksite audits to ensure compliance with working at heights.  Repairs are carried out by manufacturers of height equipment to NZ standards.
New	Engineering Controls	Risk Assessment	Completed	Ensure a risk assessment has been completed before work commences
New	Engineering Controls	Fall Protection	Completed	<ul> <li>handrails and barriers</li> <li>elevated work platforms</li> <li>scaffolding</li> <li>fall arrest and anchor point systems</li> </ul>
	Engineering Controls	Restricted access and entry points	Completed	Barricading and barriers, restricted access where there is a risk of fall from height.
New	Administrative Controls	Safety in design	Completed	Safety in design process for new and refurbishment of buildings to eliminate height risks where possible, minimise where elimination is not possible
New	Administrative Controls	Contractor management	Completed	All contractors working at height must have a Permit to Work and height training

## **Reviews**

Date	Person	Findings	Actions	Status
23/08/2016		Belinda Glass edited.		Completed
19/12/2017		Reviewed by P Benjamin		Completed
27/11/2018	Benjamin, Paul William	Reviewed		Completed
19/12/2019	Benjamin, Paul William	Reviewed		Completed
11/06/2021	Karen Bonney	Updated description, files and controls		Completed
31/01/2023	Andrea McMillan	NFA		Completed

## **Confined Space**

ID 8382 Alert Number CRITICAL RISK Next Review 31/01/2024

GPS Longitude GPS Latitude Location

Category Construction Reported By Karen Bonney Significant Risks Yes

Site Date 11/06/2021 Status Completed

Description Suffocation, asphyxiation, crushing- from collapsing walls (trenches)- slips and trips (exacberated by limited workspace).

Unrestricted access to confined spaces.
Inadequate risk assessment of confined space.

Poorly ventilated workspace.

## **Risks Identified**

Risk	Risk/Score
Financial	- Very High
Personal Injury	- High

31/03/2023 10:20:58 Page:3 of 16

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
		Confined space entry permit system		Confined space risk assessments and safe work method statements for every confined space entry. Gas monitoring and retrieval systems
	Administrative Controls	Training		Confined space entry training. Training for permit issuers/receivers.
	Administrative Controls	Confined spaces register	Completed	A register of all confined spaces on campus.
	Administrative Controls	Signage	Completed	Confined spaces have safety signage including restricted access
		Confined Spaces are locked (controlled access)	Completed	All registered confined spaces are locked to control access

#### **Reviews**

Date	Person	Findings	Actions	Status
11/06/2021	Karen Bonney	Updated files and controls		Completed
31/01/2023	Andrea McMillan	Updated raw risk		Completed

#### **Hot Work**

ID 8387 Alert Number CRITICAL RISK Next Review 31/01/2024

GPS Longitude GPS Latitude Location
Category Construction Reported By Karen Bonney Significant Risks Yes
Site Hot Work (Critical Risk) Date 11/06/2021 Status Completed

Description Risk of fire/damage to property Injury/burns from hot work

#### **Risks Identified**

Risk	Risk/Score
Financial	- Very High
Personal Injury	- Very High

## Residual Risk Rating 8.00

Type	Control	Control Name	Status	Description
	Administrative Controls	Permit to work policy	Completed	Permit to work is issued for all hot work as defined by the policy and manual
	Engineering Controls	Fire Watch		Fire watch and monitoring post work completion - permit to be adjusted to record completion of fire watch
		Contractor Management	Completed	Management of contractors and review of their permit systems
	Administrative Controls	Training	Completed	Permit issuer/receiver training

#### **Reviews**

Date   Ferson   Frindings   Actions   Status	Date	Person	Findings	Actions	Status
--	------	--------	----------	---------	--------

31/03/2023 10:20:58 Page:4 of 16

#### Isolation of services

ID 8388 Alert Number CRITICAL RISK Next Review 31/01/2024

**GPS** Longitude **GPS** Latitude

Category Construction Reported By Karen Bonney Significant Risks Yes Date 11/06/2021 Status Completed

Site Isolation of Services (Critical Risk)

Description Work disruptions due to building services being interrupted

- loss of research work

- animal environment affected

- fume hoods not working

- emergency showers not working

#### **Risks Identified**

Risk	Risk/Score
Financial	- Very High
Personal Injury	- Hiah

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
		Permit to work policy	Completed	Permit to work issued for all building service isolation as per policy and manual.
	Administrative Controls	Training	Completed	Permit issuer/receiver training
		Contractor management	Completed	Contractor management and review of of permit systems
	Administrative Controls	Consultation		Consultation with building occupiers to accommodate services interruptions and notification to all building occupiers.

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	Added risk factor		Completed

## Electrical /high voltage power

ID 8389 GPS Longitude

Category Construction

Site Electrical/High Voltage Power (Critical Risk)

Description - Electrocution, burns, fatality.

- Explosion fire

- Equipment/ Plant damage

Alert Number CRITICAL RISK Next Review 31/01/2024

**GPS Latitude** Location Reported By Karen Bonney Significant Risks Yes Date 11/06/2021

Status Completed

Location

#### **Risks Identified**

31/03/2023 10:20:58 Page:5 of 16

Risk	Risk/Score
Financial	- Very High

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
	Administrative Controls	Training	Completed	Trained electricians only to conduct electrical work
Modified	Elimination	lock out/tag out		Lock out/Tag out and/or isolation of equipment for electrical repairs. University procedures to be adhered to
	Administrative Controls	Qualifications		High voltage installations by external experts with certification and auditing as defined by the installation
	Engineering Controls	Electrical Testing	Completed	Compliance with AS/NZ Standards regarding electrical testing

#### **Reviews**

Date Person	Findings	Actions	Status
31/01/2023 Andrea McMillan	Added URLs to regulations and control measures regarding Electrical standards		Completed

## **Contractor Management**

ID 8391 Next Review 31/01/2024 Alert Number CRITICAL RISK Location

**GPS** Longitude **GPS Latitude** 

Category Construction Reported By Karen Bonney Significant Risks Yes

Site Contractor Management Date 11/06/2021 Status Completed

(Critical Risk)

Description Multiple workers on site generating risk of injury incidents

Risks/Hazards generated by contractor work may harm others in vicinity of work.

## **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Electrical	Use in wet environment	Electrocution
Physical	Equipment	Moving parts	Risk of Injury
Physical	Manual handling	Awkward loads	Potential for injuries
Physical	Transport	Moving vehicles	Potential for injury or fatality
Physical	Work practices	Inexperienced workers	Potential for injury
Physical	Housekeeping	Poor housekeeping	Potential for illness/injury
Psychosocial	Work load	Too much work	potential for illness
Physical	Electrical	Faulty equipment	Electrocution

#### **Risks Identified**

Risk	Risk/Score
Property Damage	- Very High

## Residual Risk Rating 6.00

31/03/2023 10:20:58 Page:6 of 16

Type	Control	Control Name	Status	Description
Modified	Administrative Controls	Pre approval of contractor prior to working on site		Health and Safety Compliance Approved Contractors process
	Administrative Controls	Training		University of Otago induction and site specific inductions
New	Administrative Controls	Auditing monitoring	Completed	Regular monitoring of contractors on site
	Administrative Controls	Permit to work	Completed	Permit to work systems are in place
New	Engineering Controls	Electrical testing as per AS/NZ Standards		All electrical testing to be conducted according to AS/NZ Standards

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	Added NZ Standards and control regarding electrical test and tag		Completed

#### **Lone Worker**

ID 8443 Alert Number CRITICAL RISK Next Review 31/01/2024

GPS Longitude GPS Latitude Location

Category Construction Reported By Karen Bonney Significant Risks Yes

Site Lone Worker/Remote Date 11/06/2021 Status Completed Worker (Critical Risk)

Description Injury/Medical event not being able to access emergency services or assistance.

Alone in building after hours with no emergency contacts.

Psychological impact of working alone.

#### **Risks Identified**

Risk	Risk/Score
Personal Injury	- Medium

## Residual Risk Rating 5.00

Type	Control	Control Name	Status	Description
	Administrative Controls	Communication		Use of Get Home Safe System or similar system to track lone workers. Buddy system to check in/check out.
	Administrative Controls	Define risk		Define risk work that requires two persons present (e.g. use of machinery, laboratory work)
		Rotation of lone worker shifts		Avoid long terms of working alone to minimise stress/isolation and to maintain contact with co-workers.

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	NFA		Completed

## Plant and equipment Maintenance (Critical Risk)

31/03/2023 10:20:58 Page:7 of 16

Alert Number CRITICAL RISK ID 8444 Next Review 14/06/2022 **GPS** Longitude GPS Latitude Location Reported By Karen Bonney Significant Risks Yes Category Activity/Task Date 14/06/2021 Site Status Completed

Description Lack of operator competency/training resulting in injury/harm. Risk of electric shock (refer to electrical equipment)

Unassessed plant and equipment for Health and Safety risks.

Lack of appropriate guarding resulting in injury.

Unrestricted access allowing operation of machinery without supervision resulting in harm.

Poorly maintained plant resulting in harm/injury, exposure to fumes.

Noise generated in excess of 85 decibels averaged over 8 hours or peak noise levels exceeding 140 decibels.

Potential for generation of dust and air contaminants for operators.

Adverse impact on the environment-hazardous substance spills, inappropriate disposal of waste. Lack of procedure for safe decommissioning and removal of plant at end of useful life (refer to "ionising Radiation" and "Non-ionising radiation" categories for specific information.

#### **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Equipment	Contact with hot/cold surfaces	Risk of illness
Physical	Equipment	Guarding inadequate	Risk of Injury
Physical	Equipment	entanglement	Risk of Injury
Physical	Equipment	Moving parts	Risk of Injury
Physical	Equipment	Noise	Risk of illness
Physical	Equipment	Plant/equipment not maintained	Risk of Injury
Physical	Equipment	Potential for projectiles	Risk of Injury
Physical	Equipment	Sharp blades/parts	Risk of Injury
Physical	Equipment	Dust generation	Risk of illness
Physical	Electrical	Use in wet environment	Electrocution
Physical	Electrical	Faulty equipment	Electrocution
Physical	Electrical	Overloading	Fire

#### **Risks Identified**

Risk	Risk/Score
	- Very High

#### Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
New	Engineering Controls	External accreditation or certification		Plant and equipment must be fit for purpose, maintained, repaired and certified as required. External certification may be required.
New	Administrative Controls	Inspection and audits	Completed	Auditing and inspection of plant and equipment to ensure safe for operation
New	Administrative Controls	Training		Procedure guidelines in use, and competency training. restrict use to authorized users who have demonstrated competency.
New	Engineering Controls	Guarding	Completed	Ensure appropriate guarding is in place and used.
New		Standard Operating Procedures available	Completed	SOP documented and used for training, and available for all users.
New		Internal Policy and/or Guidelines		Pre-purchase health and safety risk assessment of plant for noise, guarding, hazardous substances. Training and maintenance provision by vendor as a part of purchasing arrangements.
	Personal Protective Equipment	Personal Protective Equipment		Wearing appropriate personal protective clothing and equipment as defined in the SOP.
New	Engineering Controls	Noise levels managed below 85DBA or 140 DBA peak		Noise levels maintained below hearing loss levels at 85 DBA per 8 hour average or peak of 140 DBA.

31/03/2023 10:20:58 Page:8 of 16

-	 Personal or environmental monitoring		hearing monitoring by Occupational Health team as identified by Noise levels. Occupational health monitoring procedure
	 AS/NZS Standard 3003 Electrical installations	'	Body protected areas are used where necessary, and certified to the standard AS/NZS 3003 Electrical installations - Patient areas.  Electrical installations in high risk areas, such as laboratories, as per AS/NZS 3003.
	Internal Policy and/or Guidelines		Electrical Testing of portable electrical equipment policy and guidelines - outlines required testing of equipment

#### **Stored Energy**

ID 8445 Alert Number CRITICAL RISK Next Review 31/01/2024
GPS Longitude GPS Latitude Location
Category Construction Reported By Karen Bonney Significant Risks Yes

Site Stored Energy ( Critical Date 11/06/2021 Status Completed

Risk)

Description Sudden release of stored energy causing injury/fatality, burns, equipment/building damage.

Mat consist of gravitational potential energy, pressurized gases and liquids, stored mechanical energy,

stored electrical energy.

#### **Risks Identified**

Risk	Risk/Score
Personal Injury	- High

#### Residual Risk Rating 6.00

Туре	Control	Control Name	Status	Description
New	Administrative Controls	Risk Assessment	Completed	Risk assessment for stored energy plant/equipment
		Personal Protection Equipment		Use of personal Protective equipment and clothing as defined by the SOP
New	Administrative Controls	SOP	Completed	SOP for identified plant and equipment
New	Administrative Controls	Qualifications and Training		Qualified/competent staff to manage the equipment and associated risks
New		NZ Standards for Stored Energy	Considered	Ensure compliance with standards

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	Added NZ Standards access as URL		Completed

#### **Hazardous Substances**

ID 8446 Alert Number CRITICAL RISK Next Review 31/01/2024 GPS Longitude GPS Latitude Location

Category Substance Reported By Andrea McMillan Significant Risks Yes
Site Date 11/06/2021 Status Underway

Description Maintenance work within areas which contain a range of hazardous substances in use at various campus

locations

HSNO Classes 1 - 9

Hazardous substances used in construction areas

31/03/2023 10:20:58 Page: 9 of 16

## **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Chemical	Hazardous Chemicals	Body contact/exposure	Injury (e.g. burns)
Chemical	Hazardous Chemicals	Fire or Explosion	Injury (e.g. burns)
Chemical	Hazardous Chemicals	Spill or Release	Damage to facilities/equipment
Physical	Storage	Inappropriate storage	Potential for injury
Physical	Transport	Loss of control	Environmental
Physical	Transport	Loss of control	Potential for injury or fatality
Emergency	Physical	Potential injury or death	Potential injury or death
Physical	Housekeeping	Spills on surface	Potential for illness/injury
Physical	Work practices	Inexperienced workers	Potential for injury
Physical	Work processes	Inadequate operating procedures	Potential for injury
Chemical	Hazardous Chemicals	Body contact/exposure	Potential illness
Physical	Work layout / area	Layout not suitable for purpose	Potential for injury

## **Risks Identified**

Risk	Risk/Score
	- Very High

# Residual Risk Rating 5.00

Туре	Control	Control Name	Status	Description
New		Internal Policy and/or Guidelines	Completed	HSNO Approved COP for laboratories.
New	Controls	and/or Guidelines		Statutory budget, lab design and refurbishment safety in design to eliminate hazardous substances exposure (e.g. compliant storage cabinets, ventilation, shelving restraints)
New	Administrative Controls	Training		lab access and inductions required by all staff and contractors. Students - supervised until deemed competent.
New		External accreditation or certification	·	Hazardous Substances storage locations identified and certified under HSNO. Annual certification process. Specific emergency response training for each store/location in place
	Protective	Personal Protective Equipment	·	Supply and use of personal protective clothing and equipment in laboratories in clinical areas. Examples include safety glasses/goggles, gloves, respiratory protection, lab coats.
New		restricted substances management	·	Restricted or controlled substances (psychoactive substances, Class A & B drugs, 1080, etc.) have permits issued for the use and transportation of substances, authorised by the certificating body (ministry of health, Environmental Protection Agency).
New	Administrative Controls	Safety Data Sheets		Access to SDS available at all times, ensure familiar with information re: use and disposal of substances in use.
New	Administrative Controls	Contractor management	Completed	Ensure all contractors working on site carry relevant SDS and are familiar with the safe use of any substances they are handling
New	Administrative Controls	Grounds staff use of sprays		Growsafe accreditation , signage and communications when using chemicals. Spray when minimum amount of people in area e.g. evenings
Modified		External accreditation or certification	Underway	WorkSafe NZ approved Code of Practice under review to meet requirements of HASAW (Hazardous Substances) regulations 2017 - current draft is not practicable for University laboratories.  Growsafe qualifications for use of pesticides and herbicides for grounds staff
New		Hazardous substances inventory management		Exel spreadsheet inventories only - no IT inventory support system for hazardous substances inventory and controls. part of supply chain project.

## **Reviews**

31/03/2023 10:20:58 Page:10 of 16

Date	Person	Findings	Actions	Status
31/01/2023	Karen Bonney	Updated controls		Completed

#### **Pressure Steam**

ID 8456
GPS Longitude
Category Construction
Site Pressure Steam (Critical

GPS Latitude
Reported By Karen Bonney
Date 11/06/2021

Alert Number CRITICAL RISK

Next Review 31/01/2024 Location
Significant Risks Yes
Status Completed

Risk)

Description Risk of injury/fatality due to burns/explosion Building and equipment damage

#### **Risks Identified**

Risk	Risk/Score
Personal Injury	- High

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
New	Administrative Controls	Qualifications and Training	·	Training and competency assessments for the safe operation of pressurized equipment (e.g. autoclaves).  Qualified boiler workers/engineers for boiler/steam (maintenance, installation, certification and monitoring)
	_ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Permit to work policy	Completed	Permit to work policy and manual requirements for confined space work.
New	Administrative Controls	Audit/Monitoring	Completed	Annual certification requirements for all pressure vessels/equipment.
	Personal Protective Equipment	PPE	Completed	Use of correct personal protective equipment and clothing as assessed
New	Administrative Controls	SOP	•	Risk assessments and SOP's for the operation of pressurized vessels and equipment
New	0 0	Comply with NZ standard	Completed	
New	Engineering Controls	WorkSafe COP	Completed	

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Karen Bonney	Added URI to Worksafe and AS/NZ		Completed
	I	standards		

## Plant and equipment

ID 8462
GPS Longitude
Category Construction
Site

Alert Number CRITICAL RISK GPS Latitude Reported By Karen Bonney Date 14/06/2021

Next Review 31/01/2024 Location
Significant Risks Yes
Status Completed

31/03/2023 10:20:58 Page:11 of 16

Description Lack of operator competency/training resulting in injury/harm.

Risk of electric shock (refer to electrical equipment)

Unassessed plant and equipment for Health and Safety risks.

Lack of appropriate guarding resulting in injury.
Unrestricted access allowing operation of machinery without supervision resulting in harm.

Poorly maintained plant resulting in harm/injury, exposure to fumes.

Noise generated in excess of 85 decibels averaged over 8 hours or peak noise levels exceeding 140

Potential for generation of dust and air contaminants for operators.

Adverse impact on the environment-hazardous substance spills, inappropriate disposal of waste. Lack of procedure for safe decommissioning and removal of plant at end of useful life (refer to "ionising Radiation" and "Non-ionising radiation" categories for specific information.

#### **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Equipment	Contact with hot/cold surfaces	Risk of illness
Physical	Equipment	Guarding inadequate	Risk of Injury
Physical	Equipment	entanglement	Risk of Injury
Physical	Equipment	Moving parts	Risk of Injury
Physical	Equipment	Noise	Risk of illness
Physical	Equipment	Plant/equipment not maintained	Risk of Injury
Physical	Equipment	Potential for projectiles	Risk of Injury
Physical	Equipment	Sharp blades/parts	Risk of Injury
Physical	Equipment	Dust generation	Risk of illness
Physical	Electrical	Use in wet environment	Electrocution
Physical	Electrical	Faulty equipment	Electrocution
Physical	Electrical	Overloading	Fire

#### **Risks Identified**

Risk	Risk/Score
	- Very High
has a high potential for injury.)	

## Residual Risk Rating 6.00

Туре	Control	Control Name	Status	Description
		External accreditation or certification		Plant and equipment must be fit for purpose, maintained, repaired and certified as required. External certification may be required.
New	Administrative Controls	Inspection and audits	Completed	Auditing and inspection of plant and equipment to ensure safe for operation
New	Administrative Controls	Training	Completed	Procedure guidelines in use, and competency training. restrict use to authorized users who have demonstrated competency.
New	Engineering Controls	Guarding	Completed	Ensure appropriate guarding is in place and used.
New		Standard Operating Procedures available	Completed	SOP documented and used for training, and available for all users.
New		Internal Policy and/or Guidelines	Completed	Pre-purchase health and safety risk assessment of plant for noise, guarding, hazardous substances. Training and maintenance provision by vendor as a part of purchasing arrangements.
		Personal Protective Equipment		Wearing appropriate personal protective clothing and equipment as defined in the SOP.
New	Controls	Noise levels managed below 85DBA or 140 DBA peak		Noise levels maintained below hearing loss levels at 85 DBA per 8 hour average or peak of 140 DBA.
New		Personal or environmental monitoring	Completed	hearing monitoring by Occupational Health team as identified by Noise levels. Occupational health monitoring procedure

31/03/2023 10:20:58 Page: 12 of 16

New	Administrative	AS/NZS Standard 3003	Completed	Body protected areas are used where necessary, and certified to the standard
	Controls	Electrical installations		AS/NZS 3003 Electrical installations - Patient areas.
				Electrical installations in high risk areas, such as laboratories, as per AS/NZS 3003.
New	Administrative	Internal Policy and/or	Completed	Electrical Testing of portable electrical equipment policy and guidelines - outlines
	Controls	Guidelines		required testing of equipment

#### **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Karen Bonney	NFA		Completed

## **Traffic Management**

ID 8495 Alert Number Critical Risk Next Review 31/01/2024
GPS Longitude GPS Latitude Location
Category Site Reported By Andrea McMillan Significant Risks Yes
Site Date 31/01/2023 Status Completed

Description Field activities conducted on roads

## **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Environment	External	Weather	Personal injury
Physical	Facility	Inadequate signage	Potential for injury
Physical	Transport	Moving vehicles	Potential for injury or fatality
Physical	Transport	Moving vehicles	Collision

#### **Risks Identified**

Risk	Risk/Score
	- Very High

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
		Training and/or Supervision		Participants trained and inducted on traffic management requirements as per plan, with specific hazards and controls identified.
		Internal Policy and/or Guidelines	Completed	Internal guidelines and policy compliance, including contractors.
		External Compliance Documents	Completed	Traffic Management standards - Safety Management plan in place.
	Administrative Controls	Signage	Completed	Road signage placed as required by traffic management plan.
	Administrative Controls	Emergency Planning		Having plans in place for potential emergencies involving vehicle incidents on location.
	Administrative Controls	Licensing/certifications		Only certified traffic managers able to develop traffic management plans for submission to DCC.
		Personal Protective Equipment		Personal Protective Equipment (PPE) is worn as appropriate and required by traffic management plan

#### **Reviews**

31/03/2023 10:20:58 Page:13 of 16

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	Updated control measures		Completed

#### **Sharps**

ID 8497 Alert Number CRITICAL RISK Next Review 31/01/2024

GPS Longitude GPS Latitude Location

Category Activity/Task Reported By Karen Bonney Significant Risks Yes

Site Date 15/06/2021 Status Completed

Description Items and equipment with potential to cause cut or puncture injuries, e.g. needles, scalpel blades, broken

## **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Equipment	Sharp blades/parts	Risk of Injury

#### **Risks Identified**

Risk	Risk/Score
Personal Injury - (Potential for injury from sharp	- High
tools/plant/materials)	_

### Residual Risk Rating 5.00

Type	Control	Control Name	Status	Description
Modified	Administrative	Correct disposal of sharp	Completed	Dispose of sharp materials correctly as relative to the material. Maintain
	Controls	objects		safe level of housekeeping
Modified	Administrative	Training and/or	Completed	Use of PPE when handling sharp objects. Housekeeping when disposing
	Controls	Supervision		of materials

#### **Reviews**

	Date	Person	Findings	Actions	Status
-	22/01/2016	Bonney, Karen June			Completed
	15/06/2021	Karen Bonney	Updated		Completed
;	31/01/2023	Andrea McMillan	Updated control measures		Completed
		'	•	'	'

#### **Environment - thermal issues**

ID 8505 Alert Number Critical Risk Next Review 15/02/2024 GPS Longitude GPS Latitude Location

Category Environmental Reported By Nevan Trotter Significant Risks Yes

Site Date 12/02/2013 Status Completed

Description Thermal issues - hot, cold etc

See Policy at:

http://www.otago.ac.nz/administration/policies/otago040359.html

31/03/2023 10:20:58 Page:14 of 16

#### **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Environment	Internal	Thermal Issues	Overheating
Physical	Building related	Excessive heat in buildings	Potential for illness/discomfort
Psychosocial	Stress due to uncomfortable working conditions	Excessive heat in buildings	Stress levels

#### **Risks Identified**

Risk	Risk/Score
	- Medium

## Residual Risk Rating 4.00

Type	Control	Control Name	Status	Description
	Administrative Controls	Internal Policy and/or Guidelines	'	Awareness and compliance with University of Otago Thermal Guidelines. http://www.otago.ac.nz/administration/policies/otago040359.html
Modified	Engineering Controls	Ventilation	·	Ensure appropriate ventilation is available and used. Future building design incorporates assessment for air conditioning. Temporary equipment available e.g. use of fans
New	<b>Engineering Controls</b>	Applied thermal controls	Completed	Consider application of solar protection film, double glazing.
	Administrative Controls	Adjust work environment		Weather appropriate clothing, footwear. Adjust working hours, working from home.

#### **Reviews**

Date Person	Findings	Actions	Status
06/12/2017 Bonney, Kare	n June Added link to Thermal Police	cy in files	Completed
16/04/2020 Karen Bonne	/		Completed
15/02/2023 Andrea McMi	lan Updated controls		Completed

## **Lone Worker**

ID 8510 Alert Number CRITICAL RISK Next Review 31/01/2024
GPS Longitude GPS Latitude Location
Category Construction Reported By Karen Bonney Significant Risks Yes
Site Lone Worker/Remote Worker (Critical Risk)

Alert Number CRITICAL RISK Next Review 31/01/2024

Location
Significant Risks Yes
This is a status Completed

Description Injury/Medical event not being able to access emergency services or assistance.

Alone in building after hours with no emergency contacts.

Psychological impact of working alone.

#### **Risks Identified**

Risk	Risk/Score
Personal Injury	- Medium

Type	Control	Control Name	Status	Description
	Administrative Controls	Communication		Use of Get Home Safe System or similar system to track lone workers. Buddy system to check in/check out.
-	Administrative Controls	Define risk		Define risk work that requires two persons present (e.g. use of machinery, laboratory work)
		Rotation of lone worker shifts		Avoid long terms of working alone to minimise stress/isolation and to maintain contact with co-workers.

## **Reviews**

Date	Person	Findings	Actions	Status
31/01/2023	Andrea McMillan	NFA		Completed

# **Building**

ID 8517 Alert Number Critical Risk Next Review 02/03/2024

GPS Longitude GPS Latitude Location

Category Activity/Task Reported By Andrea McMillan Significant Risks No

Site Date 02/03/2023 Status Completed

Description Building failures, potential for injury

## **Hazard Identified**

Hazard Classifications	Hazard Category	Hazard	Risk
Physical	Building related	Spalling concrete	injury from falling debris
Physical	Building related	Excessive heat in buildings	Potential for illness/discomfort
Physical	Building related	Building components failure e.g falling shelving,	Risk of injury
Environment	Internal	Restricted space	Overcrowding
Environment	Internal	Thermal Issues	Overheating

## **Risks Identified**

Risk	Risk/Score
Personal Injury	- High

## Residual Risk Rating 6.00

Type	Control	Control Name	Status	Description
New	Administrative	Building Code	Completed	Ensure building is compliant and has a current Certificate of compliance
	Controls	compliance		
New	<b>Engineering Controls</b>	Maintenance	Completed	Maintenance schedule for buildings
New	Elimination	Design of new builds	Completed	Design process involves end users and technical experts to ensure fit for
				purpose
			•	

31/03/2023 10:20:58 Page:16 of 16